

Oil Field Environmental Incident Summary

Incident: 20131212072908 **Date/Time of Notice:** 12/11/2013 16:12

Responsible Party: Slawson Exploration Co., Inc.

Well Operator: SLAWSON EXPLORATION COMPANY, INC.

Well Name: MAGNUM 1-36-25H

Field Name: BAKER

Well File #: 22247

Date Incident: 12/11/2013 **Time Incident:** 1300

Facility ID Number:

County: MCKENZIE

Twp: 153

Rng: 101

Sec: 36

Qtr: SW SW

Location Description: Mist of oil, maybe 30 yards, off location. By 10 yards wide.

Submitted By: Ray Gorka

Received By:

Contact Person: Ray Gorka
1675 BROADWAY STE 1600
DENVER, CO 80202

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building: 0.65 Miles

Distance Nearest Water Well: 0.65 Miles

Type of Incident: Vessel Leak

Release Contained in Dike: No

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil	15	gallons	15	gallons	15	gallons
Brine	0	barrels	0	barrels		
Other	0	barrels	0	barrels		

Description of Other Released Contaminant:

.....

Inspected:

Written Report Received: 4/11/2016

Clean Up Concluded: 12/12/2013

Risk Evaluation:

none

Areal Extent:

30 yards by 10 yards

Potential Environmental Impacts:

area is snow covered, so no risk to soils.

Action Taken or Planned:

Impacted snow being removed to pad for remediation and disposal

Wastes Disposal Location: SWD or landfill.

Agencies Involved:

Updates

Date: 12/11/2013 **Status:** Inspection

Author: Clary, Shane

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

The contaminated material off of the well pad has been scraped up and disposed of. Only small areas of oil staining remaining, but the most heavily impacted areas have been removed.

Date: 12/12/2013 **Status:** Reviewed - Follow-up Required

Author: Roberts, Kris

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Spray of oil off location from a vessel leak. Follow-up is necessary.

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Arrived on-site at 5:50 pm. Sunny 83 degrees, wind out of the SW at 15 miles/hr.
GPS N 48.02489 W 103.62170. The well pad is on top of a hill surrounded by a hay field and pastureland. There is a drainage system to the north and east of the pad that runs downhill into a creek that drains into Lake Sakakawea. The inspector walked the perimeter of the well pad and into the pastureland east & north of the pad. No visible staining of soil outside pad could be found. No additional follow-up needed.